TESLA SERVICE STATION FIRE CRAWLEY, UK – 2ND MARCH 2020



A significant fire broke out at a Tesla Car Service Station in Crawley, West Sussex on 2nd of March 2019. Thick black smoke and small explosions could be seen and heard from



It took more than 50 firefighters, eight fire engines and 3 hours to get the fire under control. 50% of the building was damaged due to fire, heat and smoke. Even after 3 hours four appliances remained at the scene to locate hot spots and ensure that all the fire was out.

See link below to video of the incident: https://www.bbc.com/news/uk-england-sussex-47427311

The fire was believed to have started in the storeroom for parts and was treated as accidental. No one was hurt or injured.





The **Bridgehill Vehicle Fire Blanket** contains smoke, fumes and heat and controls the fire within seconds. We recommend Bridgehill Fire Blankets be placed strategically throughout showrooms and workshops as part of their Fire Prevention Plan.

NO WATER - NO FOAM - NO MESS

Email: info@vehiclefireblanket.com | Phone: +353 47 89293 | Website: www.vehiclefireblanket.com